Reservoir Hazard Map (Taishou ike)

Foreseen flooded area

This Hazard Map shows the area of flooding possibility by foreseeing situations of bursting reservoir bank in abnormal condition due to heavy rain and earthquake.
The flooded area on this Map indicates maximum inundation depth caused by bursting bank of full reservoir.
Please confirm the foreseen flooded area, and in case of detecting abnormality of reservoir or finding disaster possibility by evacuation advice from the city, evacuate immediately. In addition, please be aware that the foreseen flooded area could be different from that of actual flooded area.
Issued in March, 2020

Emergency contact number

Rescue etc. ⇒ Urgent report to fire department 119

In case of disaster report and self-evacuation
⇒Toyokawa City Disaster Prevention Division (0533)89-2194

Contact for reservoir administration

Toyokawa City Industrial and Environmental Department,Agricultural Affairs Division
(0533)89-2139



Note 1) Sediment disaster warning area etc. and Hazardous area by dangerous mountain stream with mud flood possibility is the information at the point of January 24, 2020.
There can be corrections in number and size of above-mentioned area by further investigation after this date.

0m 100m 200m 300m 400m 500m